

Bridge Data Collection

Bridge Data were assembled from information in MoDOT and City of Jefferson files. Locations of bridges and condition information were verified in the field. Bridge clearances were not verified with surveys but appear to be correct from visual checks.

Long Box culverts under Miller St. and the Tri-level were inspected with waders which revealed better information. The pedestrian underpass at Monroe was not traversed but appears to be in good condition when viewed from the ends.