




**Rock face 29.5 ft. from EOP EB**



**Rock face 31.5 ft from EOP WB**

**Exhibit B-1a  
One-half mile West of Dix Road**



**Rock face 25 ft. from EOP EB**



**Rock face 22 ft. from EOP WB**

**Exhibit B-1b**  
**One-quarter mile East of Dix Road**



Inadequate guardrail at bridge EB and WB

**Exhibit B-1c**  
Dix Road



**Exhibit B-2**  
**View Obstructions on the Tri-Level Interchange**



**55% sideslope - East of Lafayette**



**55% sideslope - West of Lafayette**



**EB off ramp has 55% sideslope**



**EB on ramp has 70% sideslope**

**Exhibit B-4a.1  
At Clark Avenue**



**2 foot paved median and no shoulders**

**Exhibit B-4b.1  
West of Clark Avenue**



**WB on ramp has 63% sideslope**



**Short guardrails at bridge EB and WB**

**Exhibit B-4a.2  
At Clark Avenue**



**Blunt bridge end on Clark Bridge**

**Exhibit B-4b.2  
At Clark Avenue**



**Two foot wide paved median and no shoulders**

**Exhibit B-4b.3  
East of Clark Avenue**



**Rock face 26 ft. from EOP WB**

**Exhibit B-5  
One-half mile West of Eastland Drive**