

GEORGE BUTLER ASSOCIATES, INC.
Engineers · Architects

FIGURE C3-2
Existing Levels of Service
P.M. Peak Hour