

GEORGE BUTLER ASSOCIATES, INC.
Engineers · Architects

FIGURE 1
REX WHITTON EXPRESSWAY
EXISTING BRIDGES

LEGEND:

DEFICIENCIES
HORIZ. CONSTRAINTS