

I-270 NORTH CORRIDOR STUDY EXISTING CONDITIONS - BRIDGE AND PAVEMENT



L0717 10-07-10
BT 2 BETW GDRS
10 & 11 BTM OF DK
@ JT

**I-270 BRIDGE OVER COLDWATER CREEK-
EXPOSED REBAR AND PACK-RUST ON GIRDER**




**EASTBOUND I-270 EAST OF MO 367 -
DETERIORATING UNDERLAYING CONCRETE**




A0210
St. Louis
IS 270 SOR / Coldwater Creek
Bottom spalls and saturation
in deck (typical)
10-03-2006

**PERSHALL RD BRIDGE OVER COLDWATER CREEK
EXPOSED REBAR ON BOTTOM OF DECK**



A0222
07-27-10
W. Florissant @ IS270
Chip Delams @ Long. Joint
Clean and Seal Exposed Bars

**WEST FLORISSANT AT I-270 -
EXPOSED REBAR ON JOINT**



Bridge L0745 E
08/27/2008
Span 3 deck deterioration

**EASTBOUND I-270 BRIDGE OVER RTE N-
DECK CRACKING AND PACK-RUST ON GIRDER**

