



What is the problem with the Route 66 State Park Bridge?



07-29-09 J0421
SPAN 2 PIER 3 R SIDE
L-O' BTM CHORD W/SECT-LOSS



07-29-09, J0421
SPAN 4 PIER 4 R SIDE
GUSS PLS W/SECT-LOSS



N. Vert. on W. side
of Pr. 2

07-29-09 J0421
SPAN 2 PIER 2 R SIDE
N VERT W/SECT-LOSS

6-03
12-7-04
8-14-06
9-18-07
9-15-08

Plates on the bridge are warping and rusting.

The support beams of the bridge are rusting and pitted.

Many of the support beams have completely rusted through in spots.



07-29-09 J0421
SPAN 1 FB # 8
TOP FLG THIN

SP 2
5 FB # 7
TOP FLG THIN

Concrete is breaking away, exposing the rebar that holds the bridge together



The major girders holding the bridge up rusting and are bending from excessive weight.