



Pete K. Rahn, Director

SINGLE FEASIBLE SOURCE PURCHASE POSTING NOTICE

The Missouri Department of Transportation has determined that only one source can provide the products or services described below

Title: Elgin Sweeper Repair Parts
SFS 9-070507

Description: The Missouri Department of Transportation has determined that there is only one known source that can provide the department with parts to repair an Elgin Sweeper because of territorial regions. The parts needed are listed below:

1998 Elgin Whirlwind Series L Serial # L2608D

Part#	Description
1019608	Shutter Weldment
1016257	Self Locking Pin
7076904	Screen, Water Solenoid Valve
1036887	Caster Wheel Assembly
1016121	Spring, Side Broom Return
1059047	Impeller, Balanced
1081602	Taper Lock Bushing
39180	Impeller Housing Lining, Linatex

Agency: Missouri Department of Transportation

Supplier: Key Equipment

Buyer: Carmella Green

Phone Number: 417-469-6253

E-Mail: Carmella.green@modot.mo.gov

Posting Date: 7/6/07

Response Date: 7/9/07