

I-270 NORTH CORRIDOR STUDY EXISTING CONDITIONS - PEDESTRIAN ACCESS & PUBLIC TRANSIT



NON-COMPLIANT SIDEWALK - NEW FLORISSANT



INCOMPLETE PEDESTRIAN PATH - WEST FLORISSANT



BUS STOP ALONG DUNN ROAD



BUS STOP ON DUNN ROAD APPROACHING - WEST FLORISSANT



EXISTING PEDESTRIAN BRIDGE - NON-COMPLIANT ADA ACCESS

